Setting up the Digi One SP and Vaisala Veriteq SP-2000 for TME/Win 7

You will need this hardware: (Cables not shown)

- Digi One SP – Compact Serial Server – **Product #:** 70001851 (~$200USD)

- Vaisala Veriteq SP 2000 - Temperature Humidity Logger

The **Digi One SP** and the **Veriteq SP-2000** will need to be connected together using the Digi Serial port cable. Then the Digi One SP needs to be connected to the LAN and to Digi Power supply.   Also, note the MAC address printed on the Digi One SP label. (00-40-9D-34-40-E5)

Hardware Setup details here: http://ftp1.digi.com/support/documentation/90000266_E.pdf

Once the Hardware is connected to the LAN and the power is on:

1. Go to http://www.digi.com/support/ - then search for "**Digi One SP"** in the "Select Your Product for Support" box.

2. After search, then select **Digi One SP.**

3. Now select "Diagnostics, Utilities, and MIBs".   Then from the "Operating System Specific Utilities" drop-down window select "Microsoft Windows 7".
4. Now Download and Run the "Device Setup Wizard for Windows ver. 1.10.65.0. Follow the instruction in the Wizard to finish the setup.

5. On the Digi Device Setup Wizard window, press next.


6. Select the "Digi One SP" at the correct MAC address.

7. Verify the IP Address, then click 'Next".

8. Select "RealPort (CPM Port Redirection), then click Next.

9. Click Next.

10. Verify that the correct info is listed, and note the COM Port Number which will be used in the TME configuration.

11. The Digi Wizard will now configure the settings on the PC.

12. Un-click the "Register my Digi One SP", and click "Finish".